




Sector Long Island Sound



LT Christian Barger

MSD Coram

Christian.J.Barger@uscg.mil



NRC Notifications	RRT Activations	Federal Projects	CERCLA Projects
40	0	1	0



P/C ABSOLUTE



RRT Activation:	N/A
Type and amount of product spilled:	Diesel: 50 gals
Cause of spill:	Vessel sinking; vessel neglect
Time and date of spill:	01 NOV 2013
Responsible Party:	Private Owner
Key operational activities:	Federalized Spill: FPN B14005 Investigation; OSRO Oversight
Major lessons learned:	Good team work between DEC and MSD Coram personnel.
Lead Coordinator Contact Information:	MSD Coram; MST1 Alfonso (631) 732-0190





DREDGE MUD CAT



RRT Activation:	N/A
Type and amount of product spilled:	Diesel: 500 gals
Cause of spill:	Vessel capsizing; improper vessel operation for area environmental factors
Time and date of spill:	31 JAN 2014
Responsible Party:	Summit Marine
Key operational activities:	Investigation; Oversight of responsible party clean-up actions; salvage oversight
Major lessons learned:	Improved future coordination of salvage/clean-up oversight efforts on U.S. Army Corp dredging projects.
Lead Coordinator Contact Information:	MSD Coram; MST3 Mello (631) 732-0190



PSEG UNDERGROUND CABLE

RRT Activation:	N/A
Type and amount of product spilled:	Dielectric Fluid: 400 gals
Cause of spill:	Cable rupture; equipment age
Time and date of spill:	13 JAN 2014
Responsible Party:	PSEG Power Company
Key operational activities:	Investigation; Oversight of responsible party clean-up actions
Major lessons learned:	Good partnership between Federal, State and local Municipalities.
Lead Coordinator Contact Information:	MSD Coram; MST1 Alfonso (631) 732-0190





Sector Long Island Sound



Meetings

Description	Dates
Area Committee	11 MAR 2014

Training

Description	Dates
ICS 300	10-13 FEB 14
ICS 339	3-4 MAR 2014


Drills/Exercises

PIADC Spill Exercise	20 NOV 2013




NRC Notifications

Oil Discharges



Breakdown of Reports



Questions?

