




# MSD Coram



## Incident Management Division APR 2017 – MAY 2018



	NRC Notifications	RRT Activations	FPN Projects	CPN Projects	NOV's	LOW's	Civil Penalties
MSD Coram	168	0	1	0	0	34	0

LT Donald Raby, Supervisor



# Outline

- Significant Case Summaries
  - Port Jefferson Ferry
  - Lattingtown 55 Gal Drum
  - M/Y SILVER MAMA
  - CAVALIER ROYAL
  - COIMBRA
- Planned Events
- Conclusions/Contacts



# Port Jefferson Ferry



## Date of Spill:

13 Jan 2018

## Location of Spill:

Port Jefferson Ferry Company Pier,  
Port Jefferson Harbor

## Type and Amount of Product Spilled:

15 Gal Hydraulic Oil

**Cause of Spill:** Hydraulic Ramp  
suffered equipment failure in hose.

## Other Agency Involvement:

NYDEC

**Concerns:** Facility Equipment periodic  
maintenance on systems not  
inspected by the Coast Guard, Future  
preventative measures.





# Lattingtown 55 Gal Drum



## Date of Spill:

12 May 2017

## Location of Spill:

Dosoris Pond, Lattingtown, NY

## Type and Amount of Product Spilled:

55 Gallon Drum

## Cause of Spill: Unkown

## Other Agency Involvement:

NYDEC

**Concerns:** Release of unkown material into the water, Drum was reported to be 75% full







# M/Y SILVER MAMA



## Date of Spill:

30 JUN 2018

## Location of Spill:

Sag Harbor, NY

## Type and Amount of Product Spilled:

15 Gal of Diesel

**Cause of Spill:** While fueling at the Sag Harbor Yacht Club, fuel discharged from the SILVER MAMA fuel tank vent and into the harbor.

## Other Agency Involvement:

NYDEC, Sag Harbor Police

**Concerns:** Loss of situational awareness while fueling.





# M/V CAVALIER ROYAL



## Date of Spill:

01 AUG 2017

## Location of Spill:

Potential Spill, Lake Montauk, NY

## Type and Amount of Product Spilled:

Bilge filled with Approximately 600 gal of oily water with a full sludge tank.

**Cause of Spill:** No spill, Placed COTP order for unsafe voyage condition of vessel.

## Other Agency Involvement:

STA Montauk, Montauk Marine PD

**Concerns:** Health and safety of public, possible Discharge, unsafe condition for voyage





# COIMBRA - UPDATE



## Date of Assessment:

Deploy 16JUN18

## Location of Spill:

26 NM Offshore Shinnecock

## Type and Amount of Product Spilled:

28,500 bbl of lubricating oil  
(potential)

## Cause of Spill: WWII tanker wreck

**Other Agency Involvement:** NY DEC,  
NAVY SUPSALV

## UPDATE/OUTLOOK:

- BOA selection panel convened on 22MAR18
- Create IAP
- Deploy between 16-28JUN18


COIMBRA  
photograph  
(1941)




Wreck diver  
sketch



NOAA multi-  
beam sonar  
(2009)



USN MDSU  
side-scan  
sonar  
(2017)





# Unit Responders

Total Sector IMD Personnel	
Active Duty	11
Reserve	5
Auxiliary	3
Total Pollution Responders	
Qualified	11
Auxiliary	0
Break-in	0
Total FOSCRs	
Qualified	2
Alternate qualified	2
Break-in	2





# Training/Deployments/Planned Events



Deployments	Personnel
Maria	17
Irma	4
Harvey	8

Exercises	Dates
GIUEs	29 Nov 17 (completed) Mar 18 (completed) May 18 (completed) July 18
CG IMAT Exercise	April 18
SEC NNE FSE	March 18
AMSTEP	April 18
CANUSLANT	May 18
SEC SENE FSE	May 18

# Questions?

Position	Name	Phone
MSD Supervisor	LT Donald Raby	(631) 732-0190 *500
Incident Management Division	MST1 Hillary Zarack	(631) 732-0190 *506