

| Geograp | hic Response Strategy | | | | Goldsmith Inlet LI05 |
|----------|---|---|---|----------------------|--|
| Tactic # | Purpose | Response Eq | uipment | Deployment Resources | Deployment Notes |
| PR-01 | Remove spilled oil by collecting it in a sorbent material | 300 | ft sorbent boom ft sorbent pom-poms anchor stakes | 2 shore responders | Place and stake snare or sorbent boom in areas that are likely to pool and collect oil and across the mouths of the streams and intertidal areas. Use snare boom for persistent oils and sorbent boom for non-persistent oils. Approach the streams and intertidal areas on rising tide. Replace as necessary to maximize oil recovery. |
| | material | N/A | Testing Date | Tested | |
| EX-01 | | 300 | ft protected water boom | 2 shore responders | Tend through tidal changes. Deploy boom as depicted to exclude oil from sensitive |
| | Prohibit oil slicks from | 1 marine anchor system 2 shoreline anchor system | | 1 response boats | areas. Anchor every 200-300'. Not tide dependent Deploy shoreside anchor first. |
| | entering a sensitive area | | | 1 boat operators | |
| | | | Testing Date | N Tested | |

Geographic Response Strategy

| Go | ldsm | hith | In | ot | | 5 |
|------------|------|---------|----|----|-----|---|
| U U | usii | II CI I | | eu | LIU | - |

| Local conta | cts | | | |
|---|-----------------------------|--|--|--|
| Audubon New York | <u>516-922-3200</u> | | | |
| Long Island Soundkeeper | <u>203-854-5330</u> | | | |
| Mattituck Fire Department | <u>631-298-8837</u> | | | |
| Mt Sinai Fire Department | <u>631-473-2418</u> | | | |
| Port Jefferson Fire Department | <u>631-473-3232</u> | | | |
| Riverhead Terminal | <u>800-937-2682</u> | | | |
| Riverhead Fire Department | <u>631-727-2750</u> | | | |
| Rocky Point Fire Department | <u>631-744-4102</u> | | | |
| Sound Beach Fire Department | <u>631-744-2151</u> | | | |
| Southold Fire Department | <u>631-765-3385</u> | | | |
| Wading River Fire Department | <u>631-929-4340</u> | | | |
| NY Div. of Fish and Wildlife | <u>631-444-0280</u> | | | |
| NY Div. of Marine Resources | <u>631-444-0430</u> | | | |
| NY DEC Oil Spill Hotline | <u>1-800-457-7362(24 hr</u> | | | |
| NY State Office of Emergency Mgmnt | <u>518-292-2200 (24 hr)</u> | | | |
| USFWS LI Field Office | <u>631-286-0485</u> | | | |
| USCG Sector Long Island Sound | <u>203-468-4401</u> | | | |
| National Response Center | 800-424-8802 | | | |
| | | | | |
| Bosources Dret | in the d | | | |
| Resources Prot See most current data in NOAA Environmental S | | | | |
| reference applicable data layer in NOAA Enviror | | | | |
| Application (ERMA) Navigational Ha | | | | |

Significant tide range in this area.



Goldsmith Inlet entrance at site of EX-01 looking north



Site of EX-01 looking south at mid-tide

Special Considerations

Survey site prior to deployment and modify deployment tactics and techniques as appropriate based on observed conditions. If ice is present GRS tactics and strategies must be reevaluated. Beach Berm/Underflow Dam tactics can be considered but site access may be difficult.